

	<p>Karlin district in Praha City</p> <p>(On September 4)</p> <p>Damage caused by about 2.5m of water inundating the area.</p>
	<p>Karlin district in Praha City</p> <p>An army troop was deployed to clear debris.</p>
	<p>Karlin district in Praha City</p> <p>Collapsed building.</p> <p>Wood/brick construction building. The entire building collapsed because its foundation gave way to the pressure of water in the adjoining house's basement, when water in its own basement was emptied.</p>



Karlin district in Praha City

Collapsed building
(same as the above)



Karlin district in Praha City

In front of the collapsed building.

Unusable furniture is heaved up. On the ground is mud left by the flood.



Karlin district in Praha City

Completely submerged subway.

Astonishingly high (3m) water level.



Karlin district in Praha City

Entrance to the subway
A fitting for parapet installation (about 1m high) is shown



Karlin district in Praha City

Water is pumped up from the subway.



Karlin district in Praha City

Pipes are laid from the subway.



Karlin district in Praha City

Subway route map in the station



Karlin district in Praha City

Damage is also found on the second floor.



Karlin district in Praha City

Water reached this level.

Water flew over the bank shown to the left of the railway bridge.



Karlin district in Praha City

A bank near the Hilton Hotel



Karlin district in Praha City

A view of the river from a bank (the right bank of the Vltava river near the Hilton Hotel).

A weir and a lock gate are shown (in the third channel from this side).



Karlin district in Praha City

A view of the river from the top of a bank (near the Hilton Hotel).

Water flew over here by the depth of 1.5m.



Karlin district in Praha City



Karlin district in Praha City

A road cleaning car is washing mud off a road surface.



Karlin district in Praha City

A half-broken house (semi-underground)



Karlin district in Praha City

The Hilton Hotel closed temporarily due to the inundation of the basement.



A view of Karlin district from the upstream side of the Vltava river.



Vltava river right bank
Old town

Parapet anchors



Vltava river right bank
Old town

Fitting for parapet
installation

(Water rose to the
black line.)



Vltava river

Parapets in use